Name(s) of Risk Team Members: R. Karol, P. Cirnigliaro, J. Searing				Point Value → Parameter ↓		1				2 3		4			5			
Job Title: Emergency Response, Fire Alarm			Frequen (B)	Frequency (B)		≤once/year				<pre><once month<="" pre=""></once></pre>	<pre><once month<="" td=""><td colspan="3"><pre><once pre="" shift<=""></once></pre></td><td colspan="2">>once/shift</td></once></pre>		<pre><once pre="" shift<=""></once></pre>			>once/shift		
Job Number or Job Identifier: JRA 14-07																		
Job Description: Response to Fire Alarm in Building 911			Severit (C)	Severity (C)			First Aid Only			Medical Treatment	Lost Time	Partial Disability			Death or Permanent Disability			
Training and Procedures List (optional):			Likeliho	Likelihood (D)			Extremely Unlikely			Unlikely	Possible		Probable			Multiple		
Approved by: E. Lessard Date: 11/2/06 Rev. #:0			(D)							Officery	rossible	Tiodaule						
Stressors (if applicable, please list all): Noise due to fire alarms, inclement weather, emergency vehicles, hurrying, smoke (if fire)				n for Revision (if applicable):						Comments: LECs evacuate groups of people. There are up to seven LECs. Since many LECs are present, each evacuated group (3 separate floors) is counted as 1 person for the purpose of estimating risk.								
				Before Additional Cont				nal Co	ontrols	i i	After Additional C				al Co	Controls		
Job Step / Task	Hazard	Control(s)	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	Control(s) Added to Reduce Risk		Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction
Descend / ascend stairs in Building 911	Fall from height	Railings, proper lighting, sli surfaces	p resistant stair	Y	3	2	4	2	48	-		9 1	#		91		7	
Exit building	Fall from height	Railings, ramp, proper lighti	ng	Y	3	2	3	2	36									
Exit building	Blocked egress	Remote activated doors and double doors in lobby		Y	3	2	4	1	24									
Walk from building to outdoor assembly area	Traffic accident with pedestrian	Sidewalks to control pedestrian traffic in east and south entrances – no sidewalk for west entrance, C-A OPM 3.0 warns of this hazard.		Y	3	2	4	2	48									
Responding Fire Trucks and Vehicles	Vehicular Traffic Accident	Non-Emergency cars and trucks pull to curb and allow fire truck to have right of way		Y	3	2	3	3	54	Reminded staff of of way for Emerge	NYS rules requiring right ency Vehicles	Y	3	2	3	2	36	33%
Walk from building to outdoor assembly area	Falls at the same level	Clear surfaces on grounds and driveway, proper lighting		Y	3	2	3	2	36									
Walk from building to outdoor assembly area	Fall from height	Railings, proper lighting		Y	3	2	3	2	36									
Walk from building to outdoor assembly area	Insects (Tick Bites)	Limit vegetation growth nea assemble on paved areas, cle marked crosswalks		Y	3	2	4	1	24									

Further Description of Controls Added to Reduce Risk:											
Submitted work order to add fire bells on second floor PPA area to ensure staff who are in the PPA area can clearly hear the fire bells.											
*Risk:	0 to 20	21 to 40	41-60	61 to 80	81 or greater						
	Negligible	Acceptable	Moderate	Substantial	Intolerable						